



Area of Concern – Site: P32

Map Grid Location: G7 Site visit date/ team): 8/31/15/ JZ Drainage Area (Sq. Mi.): -
Name & Location: Oak Tree Trail

1. Culvert (diameter/material/length):

☐ clogged

☐ aquatic organism passage/ perched

☐ crushed

☐ erosion (upstream/ downstream)

☐ lack of natural bed

☐ piping

☐ safety hazard

☐ overtopping
2. Trail/ Road Impact (trail/ road name): Oak Tree Trail

☐ stormwater input

☒ sediment input

☐ bridge

☐ utilities

☐ unstable trail crossing

☒ erosion

☐ safety hazard

☒ human impact (hiking/biking)

☒ missing vegetation

☐ equine/ dog impacts
3. Upland/ Stormwater

☒ nonpoint source pollution

☒ upland erosion

☐ pollutant point source

☐ unvegetated upland area
4. Lake/Pond/ Reservoir (reservoir name):

☐ erosion

☐ lack of vegetation

☐ equine impact

☐ human impact (hiking/biking)

☐ safety hazard

☐ water quality (temperature, algae, geese, fecal)
5. Other Problem Area(s) (list contributing factors)

- Potential Solutions
- ☒ relocate trail/close trail/road

☐ trail/road crossing improvement

☒ vegetation/ shoreline planting

☐ mechanical grading

☐ stormwater treatment

☐ animal watering

☐ human/ animal exclusion

☐ culvert rehabilitation/ replacement

☐ signs

☐ culvert daylighting

☐ maintenance

☐ bridge replacement/improvement

Comments

Upland sediment source on eroding, over widened trail. Trail serves as stormwater drainage to receiving water.

